

Wy-width of notch measured along transverse end area Dy-depth of notch measured from transverse end area periphery

W\_- width of notch measured along longitudinal side periphery

O\_- depth of notch measure from longitudinal side periphery